

[FAQ]

WiFi LAN connection is unstable between the router and GV-CAW 1M & 2M

Release Date: 8/3/2015

Applied to:

GV-CAW 1M & 2M WiFi Router: RT-AC68U

Issue:

GV-CAW 1M & 2M v3.0 connected to Multicam v8.6, the WiFi network connection is unstable.


Solution:

Please go change the following options as recommended.

Brand => 2.4 GHz

Wireless Mode => N only

Channel bandwidth => 20/40 MHz



For

any question on the information provided, please feel free to submit your question to our support window at support@geovision.com.tw