

[FAQ]

The IR LED in Bullet Camera

Article ID: GV15-12-04-c

Release Date: 12/04/2012

Applied to

GV-BL110D / 120D / 220D / 320D

Question

Why are there gaps among the IR LEDs in my Bullet Camera?

Answer

The IR LEDs on the Bullet Camera are not designed to be laid out in full circle. There shall be gaps among the 16 IR LEDs on the camera.

